Bit-Checks Stainless

Keep rust at bay

Bit-Check 30 Stainless 1



1 Rapidaptor stainless steel bit holder with quick-release chuck, 29 stainless steel bits.

The "Take it easy" Bit-Checks have bits with a sleeve which – from its colour and size designation – make it simple to access the right bit quickly.

05 071109 001		
® O	3888/4/1 K	1 x 1/4"x50
•	3851/1 TS PH	1 x PH 1x25; 3 x PH 2x25; 1 x PH 3x25
0	3855/1 TS PZ	2 x PZ 1x25; 3 x PZ 2x25; 1 x PZ 3x25
0	3867/1 TS	2 x TX 10x25; 2 x TX 15x25; 3 x TX 20x25;
	TORX®	3 x TX 25x25; 2 x TX 30x25; 1 x TX 40x25
0	3840/1 TS	1 x 2,5x25; 1 x 3,0x25; 1 x 4,0x25; 1 x 5,0x25;
		1 x 5,5x25

Bit-Check 12 Stainless 1



1 Rapidaptor stainless steel bit holder with quick-release chuck, 11 stainless steel bits.

The "Take it easy" Bit-Checks have bits with a sleeve which – from its colour and size designation – make it simple to access the right bit quickly.

05 057425 001		
• 0	3888/4/1 K	1 x 1/4"x50
•	3851/1 TS PH	1 x PH 1x25; 1 x PH 2x25
0	3855/1 TS PZ	1 x PZ 1x25; 1 x PZ 2x25
0	3867/1 TS	1 x TX 15x25; 1 x TX 20x25; 1 x TX 25x25;
	TORX®	1 x TX 30x25
0	3840/1 TS	1 x 3,0x25; 1 x 4,0x25; 1 x 5,0x25

Bit-Check 10 Stainless 1



1 Rapidaptor stainless steel bit holder with quick-release chuck, 9 stainless steel bits.

The "Take it easy" Bit-Checks have bits with a sleeve which – from its colour and size designation – make it simple to access the right bit quickly.

05 071110 001		
●0	3888/4/1 K	1 x 1/4"x50
•	3851/1 TS PH	1 x PH 2x25
0	3855/1 TS PZ	1 x PZ 1x25; 2 x PZ 2x25
0	3867/1 TS	1 x TX 10x25; 1 x TX 15x25; 1 x TX 20x25;
	TORX®	1 x TX 25x25; 1 x TX 30x25

Bit-Check 10 Stainless 1 SB



