

## 1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	005	016	0000001164	See list below	Connectors	KM	
02	006	016	0000001533	See list below	Connectors	KMF	
02	005	115	0000001137	See list below	Connectors	CMF	
02	005	016	0000001210	See list below	Connectors	6762	


\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

See detailed List of Part numbers at the end of the document

## 2 Type of change

- Change of production process
- 2<sup>nd</sup> source for built-in line switch to secure availability and delivery to customers.

## 3 Detailed description of change



- Change: 2<sup>nd</sup> source for the built-in line switch  
The built-in line switch can be delivered by 2 different suppliers from now on  
(switches are technically identical according SCHURTER Specifications)

## 4 Reason of change

- Production process improvement  
Identical built-in line switch integration successfully accomplished to overcome difficulties in supply.

2<sup>nd</sup> Source built-in line switch Approval Files:

- ENEC File Number ENEC-03935
- UL File Number E524325

## 5 Release date

The change will be rolled-out starting ww 14/2022 (Date code 2214 or higher on label).

Product Change Notification						PCN KM/KMF/CMF/6762	
owner	creation date	release date	released by	change order no	rev	page	D10-063-055
kummerpa	07.02.2022	15.02.2022	muehlema	2023496	A	1 of 2	

## 6 Impact of change and recommended action

- |                                     |               |  |
|-------------------------------------|---------------|--|
| <input type="checkbox"/>            | Form          |  |
| <input type="checkbox"/>            | Fit           |  |
| <input type="checkbox"/>            | Function      |  |
| <input checked="" type="checkbox"/> | Manufacturing | Note: 2 <sup>nd</sup> source for built-in line switch with updated approvals |
| <input type="checkbox"/>            | Label         |  |
| <input type="checkbox"/>            | Packaging     |  |

## 7 Reference Documents / Attachments

Kind of document	Document Title
<a href="#">Data Sheet</a>	Type KM
<a href="#">Data Sheet</a>	Type KMF
<a href="#">Data Sheet</a>	Type CMF
<a href="#">Data Sheet</a>	Type 6762

List of part numbers affected for type KM				
KM00.1105.11	KM01.1205.11			
KM00.1105.1101				
KM00.1105.1102				
KM00.1205.11				
KM00.1405.11				
KM00.2105.11				
KM00.2205.11				
KM00.3100.1101				
KM01.1105.11				
KM01.1105.1101				

List of part numbers affected for type KMF				
KMF0.2113.11	KMF1.1123.11	KMF1.1191.1102	KMF1.1263.11	
KMF0.2123.11	KMF1.1123.1101	KMF1.1193.11	KMF1.1291.11	
KMF0.2143.11	KMF1.1123.1102	KMF1.1193.1103	KMF1.1293.11	
KMF0.2163.11	KMF1.1123.1104	KMF1.1211.11		
KMF0.2193.11	KMF1.1141.11	KMF1.1213.11		
KMF0.2293.11	KMF1.1143.11	KMF1.1221.11		
KMF1.1111.11	KMF1.1161.11	KMF1.1223.11		
KMF1.1113.11	KMF1.1161.1101	KMF1.1241.11		
KMF1.1121.11	KMF1.1163.11	KMF1.1243.11		
KMF1.1121.1101	KMF1.1191.11	KMF1.1261.11		

List of part numbers affected for type CMF				
CMF2.1015.11				
CMF2.1015.12				

List of part numbers affected for type 6762				
4304.6051	3-128-296			
4304.6064	3-128-329			
4304.6072	3-131-824			
4304.6120	3-134-743			
4304.6169				
3-101-048				
3-103-816				
3-120-523				
3-122-687				
3-127-408				

Product Change Notification					PCN KM/KMF/CMF/6762		
owner	creation date	release date	released by	change order no	rev	page	D10-063-055
kummerpa	07.02.2022	15.02.2022	muehlema	2023496	A	2 of 2	

## 1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	005	016	0000001210	See list below	Power Entry Module	6762 (snap-in)	



\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected					
3-104-866	4304.6056	4304.6064	4304.6067	4304.6072	4304.6169
4304.6050	4304.6062	4304.6065	4304.6068	4304.6120	4304.6232
4304.6051	4304.6063	4304.6066	4304.6069	4304.6148	

## 2 Type of change

Change of approval markings from UR and CSA to the combined cURus on the product socket.

## 3 Detailed description of change

Old product approval	New product approval
	

## 4 Reason of change

The change is due to a standard update to UL/CSA 60320-1

## 5 Release date

The change takes effect in ww41/2019 (Date code 1941 or higher on label). The validity of the approval certificates is not affected by this change.

## 6 Impact of change and recommended action

Form	Yes	Socket new with cURus approval marking
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	No	-
Packaging	No	-

## 7 Reference Documents / Attachments

Kind of document	Remarks
<a href="#">Datasheet 6762</a>	

Product Change Notification					PCN 6762 (snap-in)		
owner	creation date	release date	released by	change order no	rev	page	D10-039-976
huberth	25.09.2019	01.10.2019	limachcl	2018434	A	1 of 1	