












Selection Guide for IEQ Accessories

Photo	Part number	Description	Target application	MI 6401	MI 6301	MI 6201
	A 1165	Sound calibrator, class 2	Sound calibrator Class 2 is intended for periodical calibration and accuracy inspection of the instrument.		•	•
	A 1180	CO ₂ probe	Probe measures concentration of carbon dioxide in the ambient air.	•		•
	A 1181	CO probe	Probe measures concentration of carbon monoxide in the ambient air.	•		•
	A 1127	Humidity and temperature probe	Probe for simultaneous relative humidity and air temperature measurements.	•		•
	A 1131	Black globe thermometer	Black globe thermometer serves for indoor temperature comfort measurements.	•		•
	A 1132	Luminance probe	Luminance probe performs measurement of luminance i.e. light reflected from the surface.	•		•
	A 1128	Thermocouple probe, type K	Type K thermocouple probe with measuring range from -20 °C to 1400 °C for contact temperature measurements of various surfaces like motors, transformers, etc.	•		•
	A 1083	Power supply adapter with 6 pcs NiMH batteries, type AA	Battery charger and a set of 6 pieces of rechargeable batteries, type AA.	•	•	•
	A 1160	Fast charger for 8 AA batteries with a set of 6 NiMH bat., type AA	Fast battery charger for up to 8 pieces of AA rechargeable batteries, and a set of 6 pcs NiMH rechargeable batteries, type AA.	•	•	•
	A 1169	Fast charger for AA, C, D and 9 V block batteries	Fast battery charger for up to 12 pcs AA, 6 pcs C or D rechargeable batteries, 4 pcs 9 V block batteries.	•	•	•
	A 1130	Telescopic rod with 2.5 m cable	The extension rod helps at measurements on remote spots like ventilation ducts and other places that cannot be easily reached by hand.	•		•

• Option