# FB012\_EN Product change notification



# Overview

PCN Number:	21-005	Date:	07.06.2021
Affected product:	Elecolit 342		
Panacol part number:	04034203, 04034205, 04034206		
Type of change:	Change manufacture location		

# Contact

Initiator:	Dr. Jutta Lörzer	Department:	QC
Email:	jutta.loerzer@panacol.de	Phone:	+49 6171 6202 0
Company:	Panacol-Elosol	Address:	Stierstädter Str. 4 61449 Steinbach, Germany

### Information

☐ Customer approval required			
Type:	☐ Major	Minor	Obsolescence
Change effects:	☐ Function	Appearance	☐ Packaging
	Other		

# **Change details**

Reason of change:	Change in structure of ownership at supplier
Description of change:	Our supplier is committed to continuous improvement in delivering products of the highest performance and quality. As part of this commitment, they are embarking on a necessary process change and supply chain realignment of our Conductive Materials. During 2021, they will move the manufacturing of these products from the current external toll blender to a supplier owned daughter company. They have thoroughly tested and qualified raw materials and processes from this new source, and we do not observe any performance or quality differences in our products.
Customer impact:	None
Affected documents:	N/A

# FB012\_EN Product change notification



Samples available:	N/A
Change implementation date:	Within 2021