



Twist to unlock Pull to open

i2500-18 iFlex Flexible Current Probe for Fluke 374 Clamp Meter

- Extend the measurement range of select Fluke Clamp Meter upto 2500A AC
- Now measure awkward size conductors / bus bars with ease
- Improved wire access & ability to measure in tight spaces



Fluke i1010

Add AC/DC Current Measurement Capability to Your FLUKE DMM

- AC/DC Current Clamp, 600A AC, 1000A DC, CAT III-600V safety rating
- 1mV/Amp output guarantees easy reading on your meter
- Maximum conductor dia Ø 30 mm



Fluke i410

Add AC/DC Current Measurement Capability to Your FLUKE DMM

- AC/DC Current Clamp, 400A AC/DC, CAT-III 600V safety rating
- 1mV/Amp output guarantees easy reading on your meter
- Maximum conductor dia Ø 30 mm

TL71 Test Lead Set

Premium DMM Test Lead Set

- Flexible silicone insulated leads are heat and cold resistant
- Distinctive comfort grip probes
- Recommended for μ V measurements
- CAT III 1000V, 10A, CAT IV 600V, 10A



Fluke TL75

Hard Point Test Lead Set

- Extremely hard alloy to resist tip wear
- 1.5m long PVC leads with comfort grip
- CAT III-1000V, CAT IV-600V safety rating



Fluke TL175

Twist Guard Test Leads with Patented Extendable Tip

- New! Wear Guard test lead wear indicator to indicate replacement of leads
- CAT III-1000V, CAT IV- 600V safety rating
- Advanced strain relief function for extra long working life



Fluke ToolPak™

TPAK - Toolpak Magnetic Meter Hanger

- Free both hands to make measurements
- Hangs you meter from metallic surface
- Kit includes universal hanger clips (two), hook & loop straps (2 lengths), adapter & strong magnets
- Ideal for 11x, 17x, 28x, 87V DMMs, 1503, 1507, 1577 & 1587 Insulation testers & 50 series digital thermometers



Fuse

Fuse for 115/15B/17B/179 Combo

Fuse, 11A, 1000V, FAST 406INX 1.5IN, BULK

Fuse for 15B/17B

Fuse, 500 MA, 1000 VOLT AC/DC, FAST, 6.35 X 32MM, BULK

Fuse for 179 Combo

Fuse, 440A, 1000V, FAST, 406X 1.375, BULK

Fuse for 1503/1507

Fuse, 315 MA, 1000 V AC/DC, FAST, 6.35 X 32 MM, BULK

