PCN	Product Change Notification De-11-05-0		
Product	DIN 41612 / IEC 60603-2	Date of Publication:	ERNI
		25.05.2011	

DIN 41612/IEC60603-2 Connectors

**Product:** Female Type ZW, D32, E48

Male Type B, B/2, B/3, CD, E160, Q, Q/2, Q/3, M, ZW, D32, E48

Type of Change: major (A) change

### Reason of Change:

End of life of stamping and molding dies of former building classes.

Improvement of production processes.

Change from ERNI EE-pressfit zone to ERNI EN "eye of the needle" pressfit zone

Adding housing add-on for easy flat rock press-in process on to the PCB.

### Alternate product replacement:

see table

Originator: Darius Clement/MK/Vertrieb/EE/de/ERNI , +49 7166 50-369, darius.clement@erni.de

The DIN 41612/IEC 60603-2 female and male right angle connectors with ERNI internal building classes 2, 3 and 5 are being discontinued.

The old female connectors are replaced by the new type 7 connectors.

The old male connectors are replaced by the new type 4 connectors.

For the new connectors, ERNI uses the new ERNI EN "eye of the needle" pressfit zone.

Please view the table below regarding technical data on the different pressfit zones:

ERNI EE	ERNI EN "eye of the needle"	
pressfit zone	Pressfit zone	
Type 2/3/5	Type 4/7	
High press-in forces	Reduced press-in forces	
Danger of PCB hole damage	Minimal danger of PCB hole damage	
PCB hole tolerance has to be complied to	Higher tolerance of the PCB hole possible	
Forces SnPb PCB	Forces SnPb PCB	
61-82 N	37-61 N	
Forces Chem Sn PCB	Forces Chem Sn PCB	
82-101 N	51-76 N	
Forces Ni Au PCB	Forces NiAu PCB	
89-105 N	43-62 N	

Contact plating: PdNiAu plated over Ni. AuCo over Ni on request.

For pressfit versions a new housing add-on has been developed to allow flat-rock press-in processes.

This means that old press-in tools will not work with the new parts.

Please refer to the specific drawings and the latest DIN catalog for the appropriate press-in tools.

Male solder Type CD and E160 have a housing add-on for better contact alignment.

All changes improve reliability and do not affect interoperability of the product.

#### **Products Affected / Types**

DIN 41612/IEC60603-2 Connectors Female Type ZW, D32, E48

Male Type B, B/2, B/3, CD, E160, Q, Q/2, Q/3, M, ZW, D32, E48

All terminations: Solder, THR, Pressfit.

#### Part.-No:

see enclosed list

# Reference Documents available at :

http://www.erni.com

Additional information, samples etc., on request

# **PCN Revision History:**

Date of Revision:	Revision Number:	Reason: