


# Announcement

## Product Change Notification

### H-Relays



Dear customer,

Hereby we would like to inform you about improvement of the following product:

#### H-Relay Series – Diameter increase of the coil wire outlet

**Items affected:**

All H-Relays

**Reason for Modification:**

Due to continuous improvements, the diameter of the coil wire outlet on the bottom of the relay is to be increased from 2.8 mm to 3.8 mm (+/- 0.2).

This modification will guarantee a better isolation and robustness, but will not affect any present electrical or mechanical properties of the relay. All relay descriptions and names will stay the same.



Furthermore, this step will improve production and deliveries flexibility.

**Modification Date:**

15<sup>th</sup> of November 2017

**First Delivery Date:**

1<sup>st</sup> of December 2017

**Support:**

For technical questions or sample requests, please contact Mr David Stastny [dstastny@standexmeder.com](mailto:dstastny@standexmeder.com)

David Stastny  
Product Manager

Arndt Werlich  
Chief Technology Officer