

## Product Change Notification (PCN)

Date: 11.01.2022  
No.: T-1456

### PhotoMOS / Photovoltaic MOSFET Driver / Phototriac Coupler / Solid State Relay Change of safety standard







We would like to inform you that it will be changed as below.  
We kindly ask you to inform your customers and obtain their acknowledgement.

#### 1. Target Products

##### PhotoMOS / Photovoltaic MOSFET Driver / Phototriac Coupler / Solid State Relay

- In addition, both customized and semi-standard products apply to this change. (excluding some customized products: for automotive part number with C \*\* and P\*\* at the end)
- If you do not know the target product number, please contact our sales representative.

#### 2. Changes, Reason and Schedule

Changes			Reason	Schedule
Safety standard change	PhotoMOS, Photovoltaic MOSFET Driver	 →  (UL/C-UL) → (UL)	To consolidate safety standards	From January, 2022 production onward
		 →  (BSI) → (VDE)		
	Solid State Relay	 →  (UL, CSA) → (UL/C-UL)		From April, 2022 production onward

#### 3. Part (Type) number, Price and Specification

Part (Type) number, price and specification remain unchanged.

**Panasonic**